

MOSCOW EMBASSY SECURITY

o o	Recently (May & June) a DCI Security Committee sponsored survey team inspected structural members of the new U.S. Embassy in Moscow now being constructed in Moscow. anomalies within some of the members that are not called for on the construction drawings.
è	 Voids & hollows were observed. These could allow wires to be drawn into place after construction is completed.
	 Unidehtified "devices" appear to be embedded in certain outer perimeter columns located within the line of sight of suspected Soviet listening posts.
_	A second inspection team will return to Moscow this month (September)
5	 An appropriate reaction must be determined to either validate the suspicions drawn from the above inspections and/or to inert possible monitoring efforts. Selected people at State should be briefed on our findings to date. After our second survey we will be in a position to offer
	suggestions for U.S. reaction.
)	Related issues to be resolved:
	- Some of the structural columns interior to the building cannot yet be inspected at the same level of sensitivity as exterior columns.
	 Possibility exists that structural columns will have to be cut and patched to negate threat.



against inspection personnel.

- Effort to remove/negate finds in the building will be delayed until all inspection is completed to avoid Soviet "PNG" action